

National Transportation Safety Board Aviation Accident Data Summary

Location: PHILADELPHIA, PA Accident Number: DCA82AA014

Date & Time: 02/03/1982, 1102 EST Registration: N1814U

Aircraft: MCDONNELL-DOUGLAS DC-10-10 Injuries: 1 Serious, 154 None

Flight Conducted Under: Part 121: Air Carrier - Scheduled

Analysis

THE AIRCREWS OF A UNITED DC-10 (FLT 99 HEAVY) AND TWO U.S. AIR DC-9'S (FLT 25 AND FLT 199) TAXIED FOR TAKEOFF AT ABOUT THE SAME TIME. DUE TO DELAYS, THE NO. 2 ENGINE OF FLT 199 WAS SHUT DOWN IN ACCORDANCE WITH APPLICABLE FUEL CONSERVATION PROCEDURES. AFTER FLT 99 WAS CLEARED FOR TAKEOFF, THE AIRCREW OF FLT 199 STARTED THEIR ENGINE, BUT IT TORCHED AND EMITTED FLAMES FROM THE TAIL CONE. THE CAPTAIN OF FLT 25 SAW THE FLAMES AND TRANSMITTED ON TOWER FREQUENCY, "99, YOU'RE RIGHT ENGINE'S ON FIRE." AT ABOUT THAT TIME, UNITED FLT 99 HEAVY WAS LIFTING OFF. THINKING HE HAD AN ENGINE FIRE, THE CAPTAIN OF UNITED FLT 99 HEAVY ABORTED ABOVE V1/VR RATHER THAN CONTINUING INTO A LOW CEILING WITH FOG AND RAIN. THE CAPTAIN THOUGHT HE COULD STOP ON THE HARD SURFACE, BUT WAS UNABLE. THE PLANE CAME TO REST ON MUDDY TERRAIN. ONE PASSENGER WAS INJURED DURING EVACUATION. DURING THIS SEQUENCE, THE TOWER CONTROLLER WAS UNABLE TO SEE THE RUNWAY DUETO THE LOW VISIBILITY (3/8 MI).

Probable Cause

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: OVERRUN Phase of Operation: TAKEOFF

Findings

- 1. (F) SAFETY ADVISORY IMPROPER PILOT OF OTHER AIRCRAFT
- 2. (F) COMMUNICATIONS/INFORMATION/ATC NOT UNDERSTOOD PILOT IN COMMAND
- 3. (F) WEATHER CONDITION FOG
- 4. IDENTIFICATION OF AIRCRAFT VISUALLY NOT POSSIBLE ATC PERSONNEL(LCL/GND/CLNC)
- 5. (F) WEATHER CONDITION LOW CEILING
- 6. (C) ABORT ABOVE V1 PERFORMED PILOT IN COMMAND
- 7. (F) WEATHER CONDITION RAIN
- 8. (F) AIRPORT FACILITIES, RUNWAY/LANDING AREA CONDITION WET
- 9. (F) TERRAIN CONDITION SOFT

Pilot Information

Certificate: Airline Transport 55 Age: Airplane Rating(s): Multi-engine Land Instrument Rating(s): Airplane Other Aircraft Rating(s): Instructor Rating(s): None 24000 hours (Total, all aircraft), 900 hours (Total, this make and model), 162 hours (Last 90 days, all Flight Time: aircraft), 62 hours (Last 30 days, all aircraft), 5 hours (Last 24 hours, all aircraft)

Aircraft and Owner/Operator Information

Aircraft Make: MCDONNELL-DOUGLAS N1814U Registration: Model/Series: DC-10-10 DC-10-10 3 Turbo Fan **Engines:**

Operator: UNITED AIRLINES INC. Engine Manufacturer: GE

Operating Certificate(s) Held:

Flag carrier (121)

Flight Conducted Under: Part 121: Air Carrier - Scheduled

Meteorological Information and Flight Plan

Conditions at Accident Site: Instrument Conditions Condition of Light: Day Observation Facility, Elevation: PHL, 0 ft msl Weather Information Source: Unknown 4 knots / , 60° Wind Speed/Gusts, Direction: Lowest Ceiling: Unknown / 0 ft agl 38°C Temperature: Visibility 0 Miles Precipitation and Obscuration:

Engine Model/Series:

CF6-6D

Departure Point: PHILADELPHIA, PA (PHL) Destination: LOS ANGLES, CA (LAX)

Airport Information

PHILADELPHIA INTL (PHL) Runway Surface Type: Asphalt Airport: Runway Used: 9L **Runway Surface Condition:** Wet

Runway Length/Width: 9500 ft / 150 ft

Wreckage and Impact Information

Crew Injuries: 11 None Aircraft Damage: Minor Passenger Injuries: 1 Serious, 143 None Aircraft Fire: None **Ground Injuries:** N/A Aircraft Explosion: None Latitude, Longitude:

DCA82AA014 Page 2 of 3

Administrative Information

Investigator In Charge (IIC):	Adopted Date: 02/03/1983
Investigation Docket:	NTSB accident and incident dockets serve as permanent archival information for the NTSB's investigations. Dockets released prior to June 1, 2009 are publicly available from the NTSB's Record Management Division at publing@ntsb.gov , or at 800-877-6799. Dockets released after this date are available at http://dms.ntsb.gov/pubdms/ .

Page 3 of 3 DCA82AA014

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report.